

WS Plus console assembly instructions (18 – 40”)


Item number: 1201015 / 1201020

Inlet side (18 - 30”)




Inlet side (32 - 40”)






Outlet side (18 - 30”)



Outlet side (32 - 40”)




Needed tools: 8 mm wrench, 10 mm wrench

1

x16 x8 x8 x8

x24 x12 x12 x12

(Inlet side)




x8 (18 - 30")


x12 (32 - 40")

ANKER ENGELUNDS VEJ 6 I DK-9200 AALBORG SV I DENMARK I TEL. +45 96 34 21 21 I WWW.SCHNORRER.DK


2




x4 x8 x8




x6 x12 x12




3



4




x4 x8 x8




x6 x12 x12

(Outlet side)



5



The balls should be adjusted so that they are 3 mm from the pipe wall when the WS Plus is in use.

ANKER ENGELUNDS VEJ 6 I DK-9200 AALBORG SV I DENMARK I TEL. +45 96 34 21 21 I WWW.SCHNORRER.DK